



Legenda:

- Perete b.a. 25 cm
- Zidarie demolata
- Zidarie noua/umplutura
- Grinzi/Bulandrugi b.a.



Ing. MIHAI URSACHESCU		Ing. MIHAI URSACHESCU	Ing. MIHAI URSACHESCU
EXPERT TEHNIC ATTESTAT MILITARI	EXPERT TEHNIC ATTESTAT MILITARI	EXPERT TEHNIC ATTESTAT MILITARI	EXPERT TEHNIC ATTESTAT MILITARI
Beneficiar: ADMINISTRATIA MUNICIPALA PENTRU CONSOLIDARE CLADIRILOR CU RISP. SESING		Beneficiar: ADMINISTRATIA MUNICIPALA PENTRU CONSOLIDARE CLADIRILOR CU RISP. SESING	
Adresa Obiectiv: B-dul Unirii, nr. 64, Bld. K4, sc. 5, ap. 134, Sector 3, Bucuresti		Adresa Obiectiv: B-dul Unirii, nr. 64, Bld. K4, sc. 5, ap. 134, Sector 3, Bucuresti	
Nr. 23006/2023		Nr. 23006/2023	
Obiectiv: Expertiza Tehnica imobil situat la adresa B-d. Hristie Botev, nr. 13-13A, Sector 3, Bucuresti		Obiectiv: Expertiza Tehnica imobil situat la adresa B-d. Hristie Botev, nr. 13-13A, Sector 3, Bucuresti	
SCARA		SCARA	
150		150	
DESEINAT de Ing. Andrei FARFARA		DESEINAT de Ing. Andrei FARFARA	
APROBAT de Ing. Marius DUMITRASCU		APROBAT de Ing. Marius DUMITRASCU	
DATA 2023		DATA 2023	
CONSOLIDARE MAXIMALA ETAL 2		CONSOLIDARE MAXIMALA ETAL 2	
R23		R23	